



# 20C DEAD-LENGTH® STEP CHUCK




TOOLS NEEDED	
2 ea.	1-1/4 Open End Wrenches
1 ea.	20C Collet Wrench
1 ea.	Machinist Vise
1 ea.	Moly-Lub Grease




## MAIN INSTRUCTIONS


- Clean the Lathe Spindle, Draw Tube, and the parts of the 20C Dead-Length Step Chuck
- Set the face of the **Stop Rod** 1-1/8" from the face of the **Stop Body**. Secure with the 1-1/4" **Hex Nut**. (This Dimension may already be set from the factory.)



- Thread the **Stop Rod/Body Sub-Assembly** into the **Dead-Length Step Chuck** and tighten securely.
  - Hold 1-1/4" Hex Nut of the Stop Rod Sub-Assembly in a vise and tighten D.L. Step Chuck using a 20C Inner Collet Spanner Wrench and turning clock-wise.
- Coat the external bearing diameter of the **Dead-Length Step Chuck**, the internal bearing diameter and collet head angle of the **Outer Collet** with Molybdenum Disulfide grease (Moly-Lub). This will insure maximum life of the mating parts.



- Thread the **Spring Retainer** into the **Outer Collet** and firmly tighten.  
(Hold the Collet with the 20C Collet Wrench [ Part No. CL-0011759-A] and use a 1-1/4" open end wrench to tighten the Spring Retainer.)



### QUICK START


Quick Start instructions quickly guide you through the procedure. Read the main instructions first to thoroughly understand how to use the product.

- Clean parts & headstock spindle
- Set face of Stop Rod 1-1/8" from Stop Body face & secure
- Thread & Secure Stop Rod-Body Assembly into D.L. Step Chuck
- Coat Bearing surfaces with Molybdenum Disulfide grease
- Assemble and secure Spring Retainer into Outer Collet
- Insert D.L. Step Chuck-Stop Assembly into Outer Collet Aligning Pin with slot in Outer Collet Face
- Slide Belleville Washer Springs on Stop Rod
- Slide on the Coil Spring & lock finger tight with the Nut, fully compressing coil spring, then back off one full turn




## MAIN INSTRUCTIONS (Continued)

- Insert **Dead Length Step Chuck & Stop Sub-Assembly** into the **Outer Collet & Spring Retainer Sub-Assembly**. Align the **Drive Pin** (shown on front page, 1st Figure) in the Step chuck with the **Slot** in the face of the **Outer Collet**.
- Slide the 2 **Belleville Spring Washers** on the **Threaded Stop Rod** with the small end of the first washer towards the **Spring Retainer** and the Large end of the second washer flush with the large end of the first washer, as Illustrated.
- Slide the compression **Coil Spring** on to the **Stop Rod** up against the **Belleville Spring Washer**.




- Thread the Hex **Nut** on the **Stop Rod** by hand to completely compress the **Coil Spring**, then back the **Nut** off one full turn.



## Boring Out the Dead-Length Step Chuck on the Lathe

- Place the three 1/8" diameter x 3/4" long pins in the holes on the face of the Dead-Length Step Chuck. (A small amount of grease on each pin will hold them in place.)
- Activate Closer to Open Position
- Slide the Dead-Length assembly into the spindle of the machine aligning the spindle key with the keyway on the Outer Collet.



### QUICK START

#### Boring Out -D.L. Step Chuck

- Place 3 Pins in face of step chuck
- With closer in "Open" position, slide D.L. Step Chuck into spindle aligning Key
- Adjust Closer until back face of D.L. Step Chuck just Contacts spindle face
- Turn Closer 1/2 Turn more & Continue to next screw hole.
- Tighten Screws in Closer
- Adjust pressure: Low to Moderate force - Approx. 3,000 Lbs.
- Drill, rough bore, and finish bore for the workpiece
- Remove & thoroughly clean
- Remount & Adjust Pressure on the workpiece: Max. 5,000 Lbs.

## BORING OUT (Continued)

- Draw the assembly into the spindle by adjusting the collet closer draw tube until the back face of the Step Chuck just contacts the face of the spindle. A very noticeable increase in resistance will be felt at this point.
- Further tighten the draw tube 1/2 turn and then continue turning until the next screw hole lines up.
- Tighten the Screws on the collet closer.
- Make certain that the three 1/8" Diameter pins are fully bottomed in the Dead-Length Step Chuck.

**CAUTION: Do not actuate the lathe's collet closer without either the three pins in the face of the Dead-Length Step Chuck or a workpiece in place. If the unit is closed without the pins or workpiece in place, both the Dead-Length Step Chuck and the Outer Collet will be permanently distorted and have to be replaced.**

- Close the Step chuck using a low to moderate chucking force, approximately 3000 Lbs.

- Using the Illustration as a guide for Maximum Diameters and Depths, Drill, Rough Bore and then Finish Bore the Step Chuck out to the proper size for the workpiece.


### Maximum Accuracy and Repeatability:

Bore out to a dimension .001" **Greater Than** the O.D. of the workpiece.


### Maximum Holding Power:

Bore out to a dimension .001" to .002" **Less Than** the O.D. of the workpiece.

**When a stepped type bore is required,** finish bore to the proper size and then face the bottom of the bore to provide a square shoulder. It is recommended that the corner where the bore and shoulder meet be undercut to insure that the workpiece fully seats against the face of the step.



- The **Stop Rod** is set at a 1-1/8" dimension from the face of the Stop Body. The **Stop Rod** can be machined to decrease its length. Custom **Stop Rod Extensions** can be made that are threaded into the 1/2"-20 TPI internal thread in the **Stop Rod**.



- Remove the **Dead-Length Step Chuck Assembly** from the spindle and thoroughly clean out chips from the slots and the bore. Deburr the edges of the machined surfaces.

# Mounting a Machined Dead-Length® Step Chuck in the Lathe


- Clean the machine spindle & the Dead-Length Step Chuck.
- Activate Closer to its "Open" Position.
- Slide the complete assembly into the spindle of the machine aligning the spindle key with the keyway on the Outer Collet.
- Place a workpiece in the bore of the Dead-Length Step Chuck.
- Draw the assembly into the spindle by adjusting the collet closer draw tube until the back face of the Step Chuck just contacts the face of the spindle. A very noticeable increase in resistance will be felt at this point.
- Further tighten the draw tube 1/2 turn and then continue turning until the next screw hole lines up.
- Tighten the Screws on the collet closer.
- Close the collet closer.
- Adjust the collet closer to the proper closing force. Maximum Recommended Force: 5,000 pounds.

## QUICK START

### Mounting-D.L. Step Chuck

- Clean Spindle & D.L. Step Chuck
- Open the Collet Closer
- Slide DL Step Chuck into spindle aligning Key with Keyway
- Put the workpiece in the Dead-Length Step Chuck
- Adjust Closer until back face of DL Step Chuck just Contacts spindle face
- Turn Closer 1/2 Turn more & Continue to next screw hole.
- Tighten Screws in Closer
- Do not exceed a chucking force of 5,000 pounds

## PARTS LIST



Description	Hardinge Part Number	Quantity
20C Dead-Length Step Chuck Assembly	2041-00-00-000000	1
- Emergency Dead Length Step Chuck	2037-00-00-000000	1
- Pin (Used when machining out the step chuck)	7731-00-00-000000	3
- Drive Pin	7734-00-00-000000	1
- Nut	1185-00-00-000000	2
- Outer Collet Body	2039-00-00-000000	1
- Spring - Coil	1187-00-00-000000	1
- Spring - Belleville	AM-9011700	2
- Spring Retainer	1815-00-00-000000	1
- Stop Body	1813-00-00-000000	1
- Stop Rod	1271-00-00-000000	1
20C Collet Wrench(For holding Outer Collet during assembly)	CL-0011759-A	1
20C Inner Collet Spanner Wrench	7897-00-00-0000001	1
Molybdenum Disulfide Grease (Moly-Lub,3 Oz.)	VS-10440	1

## HARDINGE INC.

One Hardinge Drive, PO Box 1507  
Elmira, New York 14902-1507 USA